

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2019

Submitted Date:

08/01/2019

Document Number:

689703420**FIELD INSPECTION FORM**

Loc ID 335113	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1401</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> 15 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275241	WELL	PR	10/09/2006	GW	045-13497	CASCADE CREEK 632-13-22	PR
282426	WELL	PR	06/06/2007	GW	045-11766	CASCADE CREEK 697-32-12D	PR
282427	WELL	PR	05/17/2007	GW	045-11767	CASCADE CREEK 697-29-59D	PR
282428	WELL	PR	05/17/2007	GW	045-11768	CASCADE CREEK 697-29-60D	PR
282429	WELL	PR	03/02/2016	GW	045-11769	CASCADE CREEK 697-32-09D	PR
282430	WELL	PR	06/01/2008	GW	045-11770	CASCADE CREEK 697-32-18D	PR
288549	WELL	PR	05/19/2010	GW	045-13290	CASCADE CREEK 697-32-10D	PR
288553	WELL	PR	05/17/2007	GW	045-13291	CASCADE CREEK 697-32-01D	PR
288554	WELL	PR	05/17/2007	GW	045-13292	CASCADE CREEK 697-32-03D	PR

**General Comment:**

COGCC Inspection Report Summary

On Wednesday 07/31/2109 at approximately 1430, I, Inspector Mike Longworth, conducted a field inspection at Laramie CC0632-13-22, at Location # 335113 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Danger sign by entrance is obstructed by weeds.

Install sign free of obstruction.

C.A. Date 09/30/2019

8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance.

Approximately 35' piece of poly pipe along road N39.48783 W108.24905

Lock Out/Tag Out unused flowline risers within 24 hours of receipt of this report.

Comply with Rule 603.f.

C.A.Date 08/31/2019

Subsidence of unstable cut slope behind tank battery.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 08/31/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Danger sign by entrance is obstructed by weeds.		
Corrective Action:	Install sign free of obstruction.	Date:	09/30/2019

**Emergency Contact Number:**

Comment:	970-242-1234	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance. Approximately 35' piece of poly pipe along road N39.48783 W108.24905		
Corrective Action:	Lock Out/Tag Out unused flowline risers within 24 hours of receipt of this report. Comply with Rule 603.f.	Date:	08/31/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		



Inspected Facilities									
Facility ID:	275241	Type:	WELL	API Number:	045-13497	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282426	Type:	WELL	API Number:	045-11766	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282427	Type:	WELL	API Number:	045-11767	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282428	Type:	WELL	API Number:	045-11768	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282429	Type:	WELL	API Number:	045-11769	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282430	Type:	WELL	API Number:	045-11770	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288549	Type:	WELL	API Number:	045-13290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288553	Type:	WELL	API Number:	045-13291	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Subsidence of unstable cut slope behind tank battery.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/31/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703421	Inspection 689703420 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897502</a>