

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2019

Submitted Date:

08/01/2019

Document Number:

679704940**FIELD INSPECTION FORM**Loc ID 311853 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1660 LINCOLN ST STE 2100City: DENVER State: CO Zip: 80246**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Kimmel, March	210-363-2859	mkimmel@headwatersexp.co m	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286511	WELL	SI	12/04/2013	GW	103-10888	FLETCHER GULCH 3-31	TA

**General Comment:**COGCC Inspection Report Summary.On 7-31-2019 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Genesis Gas & Oil Colorado well Fletcher Gulch 3-31 in Rio Blanco county.During this inspection the following compliance issues were observed:

- 1) Weeds next to well head and buildings. Photo 2 & 3. Complete by 8-23-2019.
- 2) Missing "911" on battery sign. Photo 4. Complete by 9-30-2019.
- 3) Holes in tank liner. Photo 5. Complete by 8-30-2019.
- 4) Stained soil. Photo 6. Complete by 8-30-2019.
- 5) Tank label incomplete. Photo 7. Complete by 9-30-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679704940.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing operator name & phone number.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/30/2019
Type	BATTERY		
Comment:	Missing "911" on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/30/2019

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soild next to tank.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2019
Type	WEEDS		
Comment:	Weeds next to well head & building.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Twp pumps on skids and 1 equipment building.		
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLs	STEEL AST		40.083200,-108.609900	
Comment:						
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate			Inadequate	
Comment:	~50 holes in liner.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 08/30/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 286511 Type: WELL API Number: 103-10888 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production December 2012. Last MIT on 12-12-2014.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704941	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898584">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898584</a>