

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/01/2019

Document Number:

679704958

FIELD INSPECTION FORM
 Loc ID 316575 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10384

Name of Operator: GENESIS GAS & OIL COLORADO LLC

Address: 1660 LINCOLN ST STE 2100

City: DENVER State: CO Zip: 80246

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Kimmel, March	210-363-2859	mkimmel@headwatersexp.co m	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286510	WELL	SI	05/14/2013	GW	103-10889	FLETCHER GULCH 33-44	SI

General Comment:

COGCC Inspection Report Summary.

On 8-1-2019 at approximately 11:45, inspector Rick Moran, conducted a routine inspection at Genesis Gas & Oil Colorado well Fletcher Gulch 33-44 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Well head gas leak. Photos 2 & 3. Complete by 8-30-2019.
- 2) Weeds. Photos 4 & 5. Complete by 8-23-2019.
- 3) Missing "911" on battery sign. Photo 6. Complete by 9-30-2019.
- 4) Lease road & location stormwater. Photos 7, 8, 9 & 10. Complete by 8-30-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704958.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Missing "911" on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/30/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds next to pump jack & meter building.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Well head gas leak.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 08/30/2019
Type: Deadman # & Marked	# 4		
Comment:			

Inspected FacilitiesFacility ID: 286510 Type: WELL API Number: 103-10889 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last recorded production December 2012. Last MIT on 11-26-2014.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Fail					

Comment: Stormwater erosion on lease road starting 600' from the location. A large portion of the stormwater sediment is flowing down the road onto the location. Then flowing off the location further down slope.

The stormwater sediment flow starts 180' up elevation from the location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/30/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704959	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898592