

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2019

Submitted Date:

07/26/2019

Document Number:

679704889

**FIELD INSPECTION FORM**

Loc ID 314339 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228448	WELL	PR	03/01/2019	OW	103-05301	ARROWHEAD 9	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 7-25-2019 at approximately 17:30, inspector Rick Moran, conducted a routine inspection at Lasso Oil & Gas well Arrowhead 9 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Stained soil at pump jack. Photo 2. Complete by 8-27-2019
- 2) Stained soil at tank. Photo 3. Complete by 8-27-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704889.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="911"/>		Date:
Corrective Action:	<input type="text"/>		<input type="text"/>

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at base of tank.		
Corrective Action:	Comply with Rule 603.f .		Date: 08/27/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Stained soil at well head.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS.		Date: 08/27/2019

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		40.069100,-108.794300
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 228448 Type: WELL API Number: 103-05301 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Pump jack idle at time of inspection.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402123201	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4891275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4891275</a>
679704890	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4891271">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4891271</a>