

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2019

Submitted Date:

07/26/2019

Document Number:

688800590**FIELD INSPECTION FORM**Loc ID 385418 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214247	WELL	PA	12/12/2006	GW	067-05581	BONDAD 33-10 3	EI

General Comment:

On July 25, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Energy Production LLC Bondad 33-10 #3. For the most recent field inspection report of this facility, please refer to document #200290228. Logos Operating LLC representative Larissa Farrell and LTE employees were on site during this field inspection. The purpose of this site visit was to observe LTE staff conduct a soil gas survey in the vicinity of a cathodic protection well associated with the Bondad 33-10 #3 as it relates to REM #13600.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	PA marker.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Open ended 2" steel flow line protruding from northwest corner of excavation.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105, or provide abandonment reporting documentation.		Date: 08/26/2019

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214247 Type: WELL API Number: 067-05581 Status: PA Insp. Status: EI

COGCC Comments

Comment	User	Date
<p>On July 25, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Energy Production LLC Bondad 33-10 #3. For the most recent field inspection report of this facility, please refer to document #200290228. Logos Operating LLC representative Larissa Farrell and LTE employees were on site during this field inspection. The purpose of this site visit was to observe LTE staff conduct a soil gas survey in the vicinity of a cathodic protection well associated with the Bondad 33-10 #3 as it relates to REM #13600.</p> <p>The area around the PA marker had been excavated previously by Logos Operating LLC. An open ended 2" steel pipe was observed protruding from the northwest corner of the excavation.</p>	hughesjo	07/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402123868	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892276
688800591	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892272