

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/26/2019

Submitted Date:

07/26/2019

Document Number:

694900107**FIELD INSPECTION FORM**

Loc ID 334156	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 17 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281407	WELL	PR	05/01/2015	GW	045-11449	SHIDELER FEDERAL 6-3 (O31E)	PR
281409	WELL	PR	01/01/2018	GW	045-11451	SHIDELER 31-15 (O31E)	PR
430553	WELL	PR	07/31/2013	GW	045-21736	Shideler Fee 31-13C (O31E)	PR
430554	WELL	PR	07/31/2013	GW	045-21737	Shideler Fee 31-13CC (O31E)	PR
430555	WELL	PR	06/04/2013	GW	045-21738	Shideler Fee 6-7D (O31E)	PR
430556	WELL	PR	06/04/2013	GW	045-21739	Shideler Fee 6-3DD (O31E)	PR
430557	WELL	PR	06/04/2013	GW	045-21740	Shideler Fee 6-3AA (O31E)	PR
430558	WELL	PR	06/04/2013	GW	045-21741	Shideler Fee 6-3A (O31E)	PR
430559	WELL	PR	07/31/2013	GW	045-21742	Shideler Fee 6-6DD (O31E)	PR
430560	WELL	PR	03/01/2014	GW	045-21743	Shideler Fee 6-3D (O31E)	PR
430561	WELL	PR	06/04/2013	GW	045-21744	Shideler Fee 6-6D (O31E)	PR
430562	WELL	PR	04/30/2013	GW	045-21745	Shideler Fee 6-6A (O31E)	PR

General Comment:

Follow up Inspection

LocationOverall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Stained Rock in Tank Battery containment, see photo

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.

Date: 07/11/2018

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

12

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

3

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: chemical tank at well heads

Corrective Action:

Date:

Type: Plunger Lift

12

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	281407	Type:	WELL	API Number:	045-11449	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	281409	Type:	WELL	API Number:	045-11451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430553	Type:	WELL	API Number:	045-21736	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430554	Type:	WELL	API Number:	045-21737	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430555	Type:	WELL	API Number:	045-21738	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430556	Type:	WELL	API Number:	045-21739	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430557	Type:	WELL	API Number:	045-21740	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	430558	Type:	WELL	API Number:	045-21741	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			

Facility ID:	430559	Type:	WELL	API Number:	045-21742	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	430560	Type:	WELL	API Number:	045-21743	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	430561	Type:	WELL	API Number:	045-21744	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	430562	Type:	WELL	API Number:	045-21745	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Gravel				
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 7/26/19 at approximately 10:45 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus Shidler 31-13 (031E) Pad, at location # 334156 in Garfield County, Colorado.</p> <p>While there, I observed normal production operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>That the staining in the tank battery from the previous inspection document # 689301272 was still in place.</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	07/26/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402124071	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892535
694900111	694900107	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892531