

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #1 Sign is posted at the Pump Jack

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #4 Photo of tank battery. Weeds inside of tank containment.



Photo #5. Photo of wellhead and pump jack. Weeds are present.

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #6 BMP or waddles in need maintenance.

Photo #7 BMP or waddles in need maintenance.

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #8 Weeds or Debris inside of tank containment.



Photo #9 Weeds or Debris around production equipment

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo # 10 Erosion is evident along un-stabilized slope at the south-east side of location.



Photo # 11 Erosion is evident along un-stabilized slope at the south-east side of location, choking out vegetation.

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



Photo #12 Culvert in need of maintenance.



Photo #13 Culvert in need of maintenance on upstream side.

Maralex Resources Inc.
API # 077-08601
Inspection # 696600436



**Photo #14 Erosion sediment moving off location and down
Access road**



**Photo #15 Erosion sediment moving off location and down
Access road**