

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2019

Submitted Date:

08/02/2019

Document Number:

696600436**FIELD INSPECTION FORM**
 Loc ID 312601 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221999	WELL	SI	05/01/2010	GW	077-08601	SOUTH SHALE RIDGE 4-13	SI

**General Comment:**

This is a follow up from inspection dated 6/5/2019 Doc# 696600068 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Weeds on location

No battery sign posted on location.

Not current MIT on file.

Stormwater erosion not being controlled on the location

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No Battery sign at entrance or at tank battery on location. there is more than one pump jack on location, each have a different sign posted.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	05/29/2019

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds on and around location		
Corrective Action:	Comply with Rule 603.f	Date:	01/21/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Location is being used for a storage facility. BLM Storage ROW SERIAL NUMBER COC-64694 is on file.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds and Debris growing inside of tank containment.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			
			Date:	08/11/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 221999 Type: WELL API Number: 077-08601 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well last produced April 2010. MIT doc#400797572 2/16/15  
No current Form 4 on file.  
Not current MIT on file

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.

Date: 06/17/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts	Fail			
Gravel	Pass					
Culverts	Fail					
Compaction	Pass					
Waddles	Fail					

Comment: Stormwater erosion not being controlled on the location at this time.  
 BMP's need repaired or are not being maintained at this time.  
 Erosion is evident along un-stabilized slope at the the South- East side of location.  
 Sediment moving down slope and onto location, choking out vegetation. See photos 10 and 11  
 BMP's (waddles) need maintenance. See photos 6 and 7  
 Culvert is in need of maintenance on upstream side. See photos 12 and 13  
 Stormwater erosion moving sediment off location and down the access road. see photos 14 and 15

Corrective Action:

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On (Friday) (Date 8/2/2019) at approximately (1155),          I, Inspector Dougo Wentzel, conducted a (Field Re-inspection)          at (Maralex) (South shale Ridge 4-13), at ( API #077-08601) in (Mesa, county) Colorado.          While there, I observed a (Production location operation only)          During this inspection the following possible compliance issues were observed:          No Battery sign on location.          Weeds and Debris around location. See photos 5 and 9.          Vegetation growing inside of tank containment. See photos 4 and 8.          Erosion is evident along un-stabilized slope at the the South- East side of location.          Sediment moving down slope and onto location, choking out vegetation. See photos. 10 and 11          BMP's (waddles) need maintenance. See photos 6 and 7          Culvert is in need of maintenance on upstream side. See photos 12 and 13          Stormwater erosion moving sediment off location and down the access road. See photos 14 and 15          No MIT on file.,          No current Form 4 on file.          (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue.          A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/02/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696600437	Inspection 696600436 photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4899393">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4899393</a>