

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/02/2019

Submitted Date:

08/02/2019

Document Number:

694900152**FIELD INSPECTION FORM**
 Loc ID 322325 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Coutts, Brandon		bcoutts@mustangresourcesllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210278	WELL	PR	12/01/2016	GW	045-06034	JUHAN RULISON UNIT 34-94-6S-94W	PR

General Comment:[Follow up inspection from Inspection # 689302725](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: There was no indication of a phone number for local emergency services (911 where available)Corrective Action: Install sign to comply with Rule 210.b.

Date: 09/02/2019

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: unmarked flow line from previous inspection #689302725 is marked with L/O T/O.

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type: Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	210278	Type:	WELL	API Number:	045-06034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 8/2/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Mustang Juhan Rulison 34-94, at Location # 322325 in Garfield County, Colorado.</p> <p>While there, I observed normal production operations. C/A(s) from previous inspection # 689302725 Valve/flow line unmarked was L/O T/O.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>There was no indication of a phone number for local emergency services (911 where available)</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	08/02/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900156	694900152	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4899477