

Inspection Photos

API: 05-055-06012

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 1. The operator name on well sign has been updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 2. The secondary containment at discharge point has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 3. Facing toward the tank. Berm has been rebuilt.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 4. The contaminated soils behind the tanks have been removed and replaced with road base material.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 5. Facing toward the pit which appears to be cleaned up of contaminated soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 6. There is a pile of contaminated soil removed from the pit that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 7. There is a container with some of the contaminated soil placed inside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019

Inspection Photos



Photo 7. There were noxious weeds along the access road that were not treated. Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 8/1/2019