

Inspection Photos

API: 05-055-06037

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019

Inspection Photos




Photo 1. There were some noxious weeds along the road that were treated and wilting. Other noxious weeds just a little further out along the cut slope were not treated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019

Inspection Photos



Photo 2. There are some noxious weeds along the road that are wilting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019

Inspection Photos



Photo 3. The operator name does not reflect current operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019

Inspection Photos




Photo 4. Noxious weeds have not been controlled along the cut slope. Wattles are degraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019

Inspection Photos



Photo 5. Further back facing south at the location. Red arrows point to noxious weed infestation (Red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 8/1/2019