

Inspection Photos

API: 05-055-06309

Operator: ALTA MESA SERVICES

Inspection Date: 8/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 1. Facing north toward access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 2. Facing north toward the location which is left graveled.



Inspection Photos



Photo 3. Facing west along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 4. Facing northwest toward the reclaimed location. The cover crop has dried up and mostly weeds are establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 5. Some of the dead trees have been removed from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 6. It appears noxious weeds have been controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 7. Facing north at the reclaimed portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 8. Facing southeast at the location. There are numerous weeds growing throughout the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 9. Facing southwest at the reclaimed portion of the location. There are numerous undesirable weeds growing throughout the area. (Russian thistle, Pigweed)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 10. Facing south at toward the gravel pad not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 11. Southwest of the location where unpermitted disturbance occurred. Facing northeast. Vegetation is establishing throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 13. View of vegetation establishment at the northwest unpermitted disturbance area. Vegetation observed included Squeal tail, Needle and thread grass, Western wheat grass, Crested wheatgrass, Scarlet globemallow, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019

Inspection Photos



Photo 14. Facing toward the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 8/1/2019