

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2019

Submitted Date:

08/05/2019

Document Number:

696500234**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 319335      Peterson, Tom      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER      State: CO      Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243295	WELL	PR	07/01/2018	GW	123-11086	BEEBE DRAW 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	100 bbls gas sales tank lacks contents, capacity and NFPA placarding. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/09/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused T-posts at 100 bbls gas sales tank. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/09/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock fencing at 100 bbls gas sales tank has been damaged. See attached photo.		
Corrective Action:	Repair fencing.	Date:	09/09/2019
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Emission Control Device	# 2				
Comment: Pilots are on.					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment: Automation arrays					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment: Bradenhead valve is exposed at surface.					
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Separator	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment: 110 bbls						
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		40.278660,-104.636260
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLs	STEEL AST		40.277570,-104.637780
Comment:	100 bbls gas sales tank has cross installed on top of tank with no PRV present. See attached photo.				
Corrective Action:	Install PRV.			Date: 09/09/2019	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal berm is undersized. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 09/09/2019

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: 243295	Type: WELL	API Number: 123-11086	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>  On Monday 8/5/2019 at approximately 11:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at Crestone Peak Resources Beebe Draw #1 API #123-11086 in Weld County Colorado.</p> <p>While there, I observed that the 100 bbls gas sales tank lacks contents, capacity and NFPA placarding, unused T-posts at 100 bbls gas sales tank, livestock fencing at 100 bbls gas sales tank has been damaged, 100 bbls gas sales tank has cross installed on top of tank with no PRV present and metal berm is undersized.</p> <p>During this inspection the following possible compliance issues were observed: Rules 210.d, 603.f, 605.a.(4)  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	petersont	08/05/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696500235	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4900397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4900397</a>