

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/02/2019

Submitted Date:

08/05/2019

Document Number:

696200529

**FIELD INSPECTION FORM**

Loc ID 435245 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 BROADWAY STE 2300  
City: DENVER State: CO Zip: 80290

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435240	WELL	PR	07/16/2014	OW	123-38529	Razor 11E-1401A	RI
435241	WELL	PR	08/09/2014	OW	123-38530	Razor 11E-0203A	RI
435242	WELL	PR	07/26/2014	OW	123-38531	Razor 11E-0202B	RI
435243	WELL	PR	08/07/2014	OW	123-38532	Razor 11E-1404B	RI
435245	LOCATION	AC			-	Razor 11E Pad	RI
435246	WELL	PR	08/07/2014	OW	123-38534	Razor 11E-1402B	RI
435247	WELL	PR	08/13/2014	OW	123-38535	Razor 11E-1403A	RI
435248	WELL	PR	08/08/2014	OW	123-38536	Razor 11E-0204B	RI
435250	WELL	PR	08/08/2014	OW	123-38537	Razor 11E-0201A	RI

**General Comment:**

*This is an interim reclamation and stormwater inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.*

**Inspected Facilities**Facility ID: 435240 Type: WELL API Number: 123-38529 Status: PR Insp. Status: RIFacility ID: 435241 Type: WELL API Number: 123-38530 Status: PR Insp. Status: RIFacility ID: 435242 Type: WELL API Number: 123-38531 Status: PR Insp. Status: RIFacility ID: 435243 Type: WELL API Number: 123-38532 Status: PR Insp. Status: RIFacility ID: 435245 Type: LOCATION API Number: - Status: AC Insp. Status: RIFacility ID: 435246 Type: WELL API Number: 123-38534 Status: PR Insp. Status: RIFacility ID: 435247 Type: WELL API Number: 123-38535 Status: PR Insp. Status: RIFacility ID: 435248 Type: WELL API Number: 123-38536 Status: PR Insp. Status: RIFacility ID: 435250 Type: WELL API Number: 123-38537 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Fail					Perimeter of disturbance. Requires reclamation.
Other	Fail					Rock-socks @sediment traps. Requires removal.
Ditches						Perimeter of disturbance. Requires reclamation
Ditches	In Process					Ditch @ pad perimeter

Comment: Stormwater ponding evident on unstabilized areas of the location. There does not appear to be sufficient stormwater controls with a stabilized outlet to mitigate ponding on the location, and to allow for sediment laden free stormwater discharge from the location in accordance with 1002.f and 1002.f.(3)

Corrective Action: Install stormwater BMPs to mitigate ponding within the pad/production areas, prevent potential industrial pollutant contact and to allow for sediment laden-free stormwater discharge from the location

Date: 08/23/2019

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200530	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4900911">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4900911</a>