

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2019

Submitted Date:

07/31/2019

Document Number:

689901061**FIELD INSPECTION FORM**

Loc ID 309657 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 202 TRAVIS STREET #402City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
		dsilverman@d90energy.com	
		kevin@d90energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300637	WELL	SI	06/01/2018	OW	073-06365	CRAIG 12-33	RI

**General Comment:**

This is a stormwater and location inspection.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The operator sign and labels have not been updated to reflect current operator.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/30/2019

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The main road was recently graded and side of the road was disturbed. This area needs to be stabilized and revegetated. There was a culvert near the location that has filled in with sediment. There is erosion issues occurring along the access road from the location. See Attached Photos

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/30/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402129176	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896823</a>
689901062	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896819</a>