

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2019

Submitted Date:

07/30/2019

Document Number:

690200025**FIELD INSPECTION FORM**
 Loc ID 315286 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections
Hale, Steve		shale@utahgascorp.com	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.co m	All inspections

General Comment:

On July 23, 2019, COGCC Environmental Staff (John Heil and Alex Fischer) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) Federal 10-1 Location ID 315286. Steven Hale with Utah Gas was on location at time of the inspection. Weather was sunny and temperatures about 75 degrees Fahrenheit.

The purpose of the inspection was to follow up on Remediation# 12185 to close pit ID# 104323 (Doc# 401872065).

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Open port on upper section of 400 BBL condensate tank #80410.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/31/2019
Type	TRASH		
Comment:	Trash within secondary containment of tank battery. Steven Hale was notified onsite and removed trash.		
Corrective Action:	Comply with Rule 603.f .	Date:	
Type	OTHER		
Comment:	Stained soil beneath loadout valve on 400 BBL condensate tank #80096 (See photos). Steven Hale was notified onsite.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.	Date:	08/31/2019
Type	OTHER		
Comment:	AST heater (fire tube) cover removed.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/31/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: COGCC staff observed a 30 feet by 40 feet by 12 feet deep excavation located northeast of the tank battery, where the pit was located. To the south of the pit is a bermed landfarm of the excavated material measuring roughly 160 feet by 30 feet by 2 feet thick. (See photos) Operator indicated that once the landfarm material passes COGCC 910-1 criteria, it will be used to fill in the excavation.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402129321	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896928
690200029	20190723 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896926