



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Well is TA unused equipment: PU and parts.		
Corrective Action:	Comply with rule 603 f	Date:	10/30/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Horizontal Separator	# 0		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Type: Emission Control Device	# 0		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 284070 Type: WELL API Number: 123-23744 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA At time of inspection it appears all flow lines have been removed from WH rods have been removed.

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Tuesday July 30, 2019 at approximately 12:44PM, I, Inspector Randy Silver conducted an on-site inspection at KP Kaufman site Colclosure #42-21, at API # 05-123-23744 in Weld County Colorado.                      While there, I observed Production well site.                      During this inspection the following possible compliance issues were observed:                      Unused equipment: Rule 603 f Correction action date of 10-30-19 see photo 2                      At time of inspection I observed flow lines have been removed from WH and PU is dismantled and lying on ground. Rods have been removed from Well bore.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	07/30/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402129097	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896727</a>
693500937	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896709">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896709</a>