

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #1 – Facility sign.



Photo #2 – Tank battery signs.



Inspection Photos

Location Name: Mesa H2-797 Pad

Location ID: #439917

Inspection Date: July 26, 2019



Photo #3 – Junk pipe located northeast of tank battery.



Photo #4 – Metal pipe stored inside of lined secondary containment area (west side).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #5 – Metal scrap and unused equipment stored inside of lined secondary containment area (southwest corner).



Photo #6 – Angle iron and hoses with metal fittings stored inside of lined secondary containment area (east side).

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #7 – Trash outside of secondary containment (east side).



Photo #8 – Unmarked, unused 2" flowline riser east of tank battery.

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #9 – Angle iron stored inside of lined secondary containment area (northwest corner).




Photo #10 – Faded NFPA placard on day tank stored inside southwest corner of lined secondary containment area.

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #11 – Filter sock containment device on top of liner, located west of separators.



Photo #12 – Day tank with process piping located west of separators.

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #13 – Filter pots on top of liner, located west of separators.



Photo #14 – Pump on top of liner. Note pump wheels and hitch jack directly on liner may cause damage due to vibration.

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #15 – Unused, unmarked, and uncapped flowline riser located at south end of separators.



Photo #16 – Equipment storage north of frac tanks (1).

Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #17 - Equipment storage north of frac tanks (2).



Photo #18 – Frac tanks located at southeast side of location.



Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #19 - Equipment storage south of frac tanks.



Photo #20 – Bucket of unidentified fluid stored on west side of frac tanks.



Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #21 - Junk pipe stored along south side of location.



Photo #22 – Additional ancillary equipment (day tank, diesel AST, trash container) located south of wellhead area.



Inspection Photos
Location Name: Mesa H2-797 Pad
Location ID: #439917
Inspection Date: July 26, 2019



Photo #23 – Day tanks inside of secondary containment on north side of fenced wellhead area.



Photo #24 – Localized accumulations of oil-stained soil north of fenced wellhead area.