

Inspection Photos  
Location Name: 596-33C  
Location ID: 335880  
Inspection Date: July 29, 2019



Photo #1 – Aerial view of the location (GISOnline Maps).



Photo #2 – Location sign.

Inspection Photos  
Location Name: 596-33C  
Location ID: 335880  
Inspection Date: July 29,2019



Photo #3 - Localized accumulation of oily waste (oil-stained soil) in the 596-33C-14 cellar.



Photo #4 - Localized accumulation of oily waste (oil-stained soil) in the 596-33C-16 cellar.



Inspection Photos  
Location Name: 596-33C  
Location ID: 335880  
Inspection Date: July 29, 2019



Photo #5 - Localized accumulation of oily waste (oil-stained soil) in the 596-33C-18 cellar.



Photo #6 - - Localized accumulation of oily waste (oil-stained soil) in the 596-33C-21 cellar. Uncovered cellars with no wildlife egress.



Inspection Photos  
Location Name: 596-33C  
Location ID: 335880  
Inspection Date: July 29,2019



Photo #7 - Localized accumulation of oily waste (oil-stained soil) in the 596-33C-27 cellar.



Photo #8 – View of unmarked flowline located north of the separators.



**Inspection Photos**  
**Location Name: 596-33C**  
**Location ID: 335880**  
**Inspection Date: July 29,2019**



**Photo #9 - Assorted metal equipment stored in direct contact with tank battery liner.**



**Photo #10 - Assorted metal equipment stored in direct contact with tank battery liner.**



**Inspection Photos**  
**Location Name: 596-33C**  
**Location ID: 335880**  
**Inspection Date: July 29,2019**



**Photo #11 – View of trash.**



**Photo #12 – View of trash.**

