

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2019

Submitted Date:

08/01/2019

Document Number:

679704940

**FIELD INSPECTION FORM**

Loc ID 311853 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10384  
Name of Operator: GENESIS GAS & OIL COLORADO LLC  
Address: 1660 LINCOLN ST STE 2100  
City: DENVER State: CO Zip: 80246

**Findings:**

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kimmel, March	210-363-2859	mkimmel@headwatersexp.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286511	WELL	SI	12/04/2013	GW	103-10888	FLETCHER GULCH 3-31	TA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 7-31-2019 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Genesis Gas & Oil Colorado well Fletcher Gulch 3-31 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Weeds next to well head and buildings. Photo 2 & 3. Complete by 8-23-2019.
- 2) Missing "911" on battery sign. Photo 4. Complete by 9-30-2019.
- 3) Holes in tank liner. Photo 5. Complete by 8-30-2019.
- 4) Stained soil. Photo 6. Complete by 8-30-2019.
- 5) Tank label incomplete. Photo 7. Complete by 9-30-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704940.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Missing "911" on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/30/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing operator name & phone number.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/30/2019

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds next to well head & building.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2019
Type	OTHER		
Comment:	Stained soild next to tank.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Twp pumps on skids and 1 equipment building.		
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		40.083200,-108.609900
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	~50 holes in liner.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 08/30/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 286511 Type: WELL API Number: 103-10888 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402131766	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898607</a>
679704941	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898584">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898584</a>