

Inspection Photos

API: 05-071-06340

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 8/8/2019

Inspection Photos



Photo 1. Facing northwest at mouth of the canyon. The main road has recently be graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 8/8/2019

Inspection Photos



Photo 2. Sediment has already filled into the diversion ditch since grading occurred. A sediment trap or rock checkdamns may be need to control erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 8/8/2019

Inspection Photos



Photo 5. Erosion channel has already developed where erosion was repaired. BMP's need to be installed to control erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 8/8/2019