

Laramie Energy LLC
API # 077-08645
Inspection # 696600459



Photo #1 Battery sign is posted at the entrance to location

Laramie Energy LLC
API # 077-08645
Inspection # 696600459



Photo #2 Photo at entrance of location.



Photo #3 Photo at entrance of location.


Inspection # 696600459

Photo #4 Photo of the tank battery.




Photo #5. Photo at wellheads

Laramie Energy LLC
API # 077-08645
Inspection # 696600459



Photo #6 Erosion sediment moving down access road. BMP's need maintenance.



Photo #7 Erosion sediment moving down access road. BMP's need maintenance.

Laramie Energy LLC
API # 077-08645
Inspection # 696600459



Photo #8 Erosion sediment moving down access road at entrance to location. BMP's need maintenance or are not in place.



Photo #9 Erosion sediment moving down access road at entrance . BMP's need maintenance or are not in place.

Laramie Energy LLC
API # 077-08645
Inspection # 696600459



Photo #10. Erosion moving sediment off location by the Separator and tank battery. Sediment is choking out vegetation. No BMP's in place at time of inspection.



Photo #11. Erosion moving sediment off location by the Separator and tank battery. Sediment is choking out vegetation. No BMP's in place at time of inspection.