

Inspection Photos
Operator: Enduring Resources
Location/API #: 067-07473
Date: 8-5-2019



Photo 1. View of the eastern project area from the southeastern edge facing northward.



Photo 2. View of BMP that is not sufficient and erosion is continuing within the southeastern project area.



Photo 3. View of the southern project area from the southeastern corner facing westward.