

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2019

Submitted Date:

08/13/2019

Document Number:

689703432**FIELD INSPECTION FORM**
 Loc ID 437097 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437091	WELL	PR	09/29/2014	GW	045-22406	Hicks PA 444-6	PR
437092	WELL	PR	09/30/2014	GW	045-22407	Hicks PA 544-6	PR
437093	WELL	PR	12/11/2014	GW	045-22408	Hicks PA 333-6	PR
437094	WELL	PR	11/03/2014	GW	045-22409	Hicks PA 44-6	PR
437095	WELL	PR	10/09/2014	GW	045-22410	Hicks PA 34-6	PR
437096	WELL	PR	10/09/2014	GW	045-22411	Hicks PA 43-6	PR
437098	WELL	PR	11/03/2014	GW	045-22412	Hicks PA 343-6	PR
437099	WELL	PR	10/09/2014	GW	045-22413	Hicks PA 33-6	PR

General Comment:

On Tuesday 08/13/2019 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a Follow up field inspection at Terra Hicks PA 24-6, at Location # 437097 in Garfield County, Colorado.

Action item was met from 04/18/2019 Inspection 689703051
Combustor and flow line have been removed.

Action item not met from 04/18/2019 Inspection 689703051
Dead weeds covering north west area of location.
Comply with Rule 603.f.
C.A. Date 04/30/2019

4" riser at tank battery without Lock out Tag out and no cap on line.
Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.
C.A. Date 08/14/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.



Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Action item not meet from 04/18/2019 Inspection 689703051 Dead weeds covering north west area of location.		
Corrective Action:	Comply with Rule 603.f .		Date: 04/30/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	4" riser at tank battery without Lock out Tag out and no cap on line.		
Corrective Action:	Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.		Date: 08/14/2019
Type: Emission Control Device	#		
Comment:	Combustor and flow line have been removed.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	437091	Type:	WELL	API Number:	045-22406	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437092	Type:	WELL	API Number:	045-22407	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437093	Type:	WELL	API Number:	045-22408	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437094	Type:	WELL	API Number:	045-22409	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437095	Type:	WELL	API Number:	045-22410	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437096	Type:	WELL	API Number:	045-22411	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437098	Type:	WELL	API Number:	045-22412	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	437099	Type:	WELL	API Number:	045-22413	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703434	Inspection 689703432 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908163