

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2019

Submitted Date:

08/13/2019

Document Number:

685101585

FIELD INSPECTION FORM

Loc ID 429005	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 1001 NOBLE ENERGY WAY City: HOUSTON State: TX Zip: 77070				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429006	WELL	TA	07/03/2018	OW	123-35624	ADAMS D 30-30D	TA
429007	WELL	PR	10/01/2017	OW	123-35625	ADAMS D 30-29D	PA
429076	WELL	SI	09/01/2018	OW	123-35672	DECHANT D 30-17D	TA
429080	WELL	SI	09/01/2018	OW	123-35675	ADAMS D 30-31D	TA
447681	TANK BATTERY	AC	09/09/2016		-	ADAMS D 30-29D	AC
463299	OFF- LOCATION FLOWLINE	AC	03/14/2019		-	Production Line 30-29D	AC
463300	OFF- LOCATION FLOWLINE	AC	03/14/2019		-	Production Line 30-29D	AC
463301	OFF- LOCATION FLOWLINE	AC	03/14/2019		-	Production Line 30-29D	AC
463302	OFF- LOCATION FLOWLINE	AC	03/14/2019		-	Production Line 30-29D	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' Barb wire

Corrective Action:

Date:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

3

Comment:

Corrective Action:

Date:

Type: Bird Protectors

9

Comment:

Corrective Action:

Date:

Type: Emission Control Device

4

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

5

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER	3	200 BBLs	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.203400,-104.596610
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
Comment:			
Corrective Action:			

Inspected Facilities

Facility ID: <u>429006</u>	Type: <u>WELL</u>	API Number: <u>123-35624</u>	Status: <u>TA</u>	Insp. Status: <u>TA</u>
Facility ID: <u>429007</u>	Type: <u>WELL</u>	API Number: <u>123-35625</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>429076</u>	Type: <u>WELL</u>	API Number: <u>123-35672</u>	Status: <u>SI</u>	Insp. Status: <u>TA</u>
Facility ID: <u>429080</u>	Type: <u>WELL</u>	API Number: <u>123-35675</u>	Status: <u>SI</u>	Insp. Status: <u>TA</u>
Facility ID: <u>447681</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>463299</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>463300</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>463301</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>463302</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	08/13/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101586	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908325