

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2019

Submitted Date:

08/13/2019

Document Number:

679705050**FIELD INSPECTION FORM**

Loc ID 316731	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED			
Operator Information: OGCC Operator Number: <u>56680</u> Name of Operator: <u>MERRION OIL & GAS CORP</u> Address: <u>610 REILLY AVENUE</u> City: <u>FARMINGTON</u> State: <u>NM</u> Zip: <u>87401</u>				Findings: 6 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested			
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE			
Contact Information:							
Contact Name	Phone	Email	Comment				
Courtney, Rogers	316-636-2242	salthawk@cox.net					
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us					
Thompson, Bud		BLThomps@BLM.gov					
Winter, Mary	316-262-4800	highrowler2@cox.net					
Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232418	WELL	PR	06/01/2019	GW	103-66126	LLOYD-FEDERAL 22-X-17	UN
General Comment:							
<p>COGCC Inspection Report Summary.</p> <p>On 8-9-2019 at approximately 16:30, inspector Rick Moran, conducted a routine inspection at Sonterra Energy location signed as Federal 22 X 17 in Rio Blanco county.</p> <p>During this inspection the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1) Unused equipment. Photos 2, 3, 4, 5. Complete by 11-8-2019. 2) Stained soil at separator. Photo 6. Complete by 9-12-2019. <p>A voice message was left at 316-262-4800 (contact phone number at well 05-103-08096) on 8-10-2019 @ 10:00 requesting a current contact email address. The same phone number was called & went to voice mail on 8-12-2019 @ 9:30.</p> <p>No surface evidence of a well at this location. The battery sign is for Merrion Oil & Gas well 103-66126 located 3.3 miles to the southeast. Adjacent to this location is a gas meter building signed with White Eagle & Black Hills Energy with a contact number of 1-800-694-8989.</p> <p>Equipment history:</p> <ol style="list-style-type: none"> 1) On the 1990's satellite image no equipment is present. 2) The inspection log inside the separator is last dated May 2006 (Photo 7). 3) The equipment was first identified during inspection 200035623 dated 12-10-2002. 4) The 2009 satellite image shows the equipment. <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report 679705050.</p>							

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at separator.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	09/12/2019
Type	UNUSED EQUIPMENT		
Comment:	No evidence that the tank, compressor, or separator are in use. Equipment needs removed from the location.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/08/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	300 BBLS	STEEL AST		40.165200,-108.251300
Comment:	No label on tank. Tank appeared to be empty or near empty.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Berm covered with thick vegetation.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	232418	Type:	WELL	API Number:	103-66126	Status:	PR	Insp. Status:	UN
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>No surface evidence of a well at this location.</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705051	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908388