

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2019

Submitted Date:

08/07/2019

Document Number:

690200036**FIELD INSPECTION FORM**
 Loc ID 335880 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Mize-Spansky, Kristine		kmizespansky@caerusoilandgas.com	
Colby, Lou		lou.colby@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
,		cogcc.inspections@caerusoilandgas.com	

General Comment:

On July 29, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of CAERUS PICEANCE LLC (Caerus operator #10456) 596-33C Location ID 335880. Follow-up to operator's proposed water sharing plan Sundry Notice (docs #402090550).

Weather was sunny and temperatures about 70 degrees Fahrenheit.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. Unmarked flowline located north of the separators and northwest of the tank battery (See photos).		
Corrective Action:	For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	08/08/2019
Type	STORAGE OF SUPL		
Comment:	Assorted metal equipment stored in direct contact with tank battery liner has potential to cause damage to liner (See photos)		
Corrective Action:	Comply with Rule 603.f. (equipment inside tank battery).	Date:	09/07/2019
Type	TRASH		
Comment:	Site wide trash (See photos).		
Corrective Action:	Comply with Rule 603.f .	Date:	08/04/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Well cellars uncovered with no wildlife egress, 596-33C-(16,21,23,).		
Corrective Action:	Install wildlife protection equipment.	Date:	08/10/2019
Type: Other	#		
Comment:	Localized accumulations of oily waste (oil-stained soil) in the 596-33C-(14,16,18,21,27) cellar (See photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (wellhead) Remove and properly dispose of oily waste, per Rule 907.e.		Date: 09/07/2019

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402137143	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4902107
690200042	20190729 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4902106