

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/13/2019

Submitted Date:
08/14/2019

Document Number:
689802973

FIELD INSPECTION FORM

Loc ID 426365 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------------|-------|--|---------------------------------|
| Inspections, General | | sandridgeenvironmental@sandridgeenergy.com | All Inspections |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Ash, Margaret | | margaret.ash@state.co.us | |

General Comment:

[COGCC Inspection Report 689802973 Summary](#)
On Tuesday 8/13/2019 at approximately 11:40, I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration and Production LLC Peterson Ridge 01-20H, at 426365 in Jackson County Colorado.
While there, I performed a follow up inspection to vehicle tracking issues observed in inspection document number 689802773. Vehicle tracking corrective actions have not been resolved.
During this inspection the following possible compliance issues were observed:
Tracking off location occurring onto highway 40 in both directions. Inspector observed tracking on 8/12/2019 while traveling on highway 14, photos 1-4. No tracking BMPs observed during inspection performed on 8/13/2019. See photos 5-8. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority by 5/8/2019.
I spoke with Russel Shipley and Spence Laird of Sandridge on 8/14/2019 to discuss lack of tracking measures.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report 689802973.

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Tracking off location occurring onto highway 40 in both directions. No tracking BMPs observed.

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority.

Date: 05/08/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689802974 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909144 |