

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 1. Ongoing leak occurring at wellhead.



Photo 2. Close up of photo 1, leaking area circled in red.

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 3. Ongoing leak occurring at tank flowline.



Photo 4. Close up of photo 3, leaking area circled in red.



Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 5. Stained soil at pump jack motor.



Photo 6. Stained soil and free fluid at separator.



Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 7. Stained soil and free fluid at separator.



Photo 8. Stained soil in flare pit.

