

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

694900208

FIELD INSPECTION FORM

Loc ID 336038 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278178	WELL	PR	05/01/2019	GW	045-10848	RIVER RANCH B1	PR
278181	WELL	PR	05/01/2019	GW	045-10851	RIVER RANCH B2	PR
299122	WELL	AL	05/20/2014	LO	045-17564	River Ranch B3	AL
299123	WELL	AL	05/20/2014	LO	045-17565	River Ranch B10	AL
299124	WELL	AL	05/20/2014	LO	045-17566	River Ranch B4	AL
299125	WELL	AL	05/20/2014	LO	045-17567	River Ranch B7	AL
299126	WELL	AL	05/20/2014	LO	045-17568	River Ranch B8	AL
299127	WELL	AL	05/20/2014	LO	045-17569	River Ranch B9	AL
299128	WELL	AL	05/20/2014	LO	045-17570	River Ranch B11	AL

General Comment:

Routine Inspection

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked # 3

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,

Comment: Centralized containment

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	<u>278178</u>	Type:	<u>WELL</u>	API Number:	<u>045-10848</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>278181</u>	Type:	<u>WELL</u>	API Number:	<u>045-10851</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>299122</u>	Type:	<u>WELL</u>	API Number:	<u>045-17564</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299123</u>	Type:	<u>WELL</u>	API Number:	<u>045-17565</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299124</u>	Type:	<u>WELL</u>	API Number:	<u>045-17566</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299125</u>	Type:	<u>WELL</u>	API Number:	<u>045-17567</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299126</u>	Type:	<u>WELL</u>	API Number:	<u>045-17568</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299127</u>	Type:	<u>WELL</u>	API Number:	<u>045-17569</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>299128</u>	Type:	<u>WELL</u>	API Number:	<u>045-17570</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 8/14/19 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a Routine inspection at Ursa River Ranch B pad, at location # 336038 in Garfield County, Colorado. While there, I observed Normal production operations.</p> <p>This is a summary of inspection report.</p>	ramseys	08/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900209	694900208	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910947