

Inspection Photos

API: 05-009-06554

Operator: LORENTZ OIL & GAS

Inspection Date: 8/14/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06554 | Date: 8/14/2019

Inspection Photos



Photo 1. It appears the access road was reclaimed and vegetation is establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06554 | Date: 8/14/2019

Inspection Photos



Photo 2. It appears the location was decompacted. This area does not have vegetation establishing. Not sure if and when it was seeded. There may be soil issues.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06554 | Date: 8/14/2019

Inspection Photos



Photo 3. Facing east at the location. This area is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06554 | Date: 8/14/2019

Inspection Photos



Photo 4. Facing south at the surrounding pasture adjacent pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06554 | Date: 8/14/2019