

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-09948
Date: 8-14-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of erosional channel forming within the access road slope.



Photo 3. View of bare soils on the northern cut-slope.



Photo 4. View of what appears to be cuttings debris placed on the northern cut-slope.



Photo 5. View of plastic fencing debris around wellhead location.



Photo 6. View of dense Russian knapweed (*Rhaponticum repens*) infestation in the northwestern project area.



Photo 7. View of Canada thistle (*Cirsium arvense*) infestation on the access road.



Photo 8. View of weeds on the access road, largely kochia (*Kochia scoparia*).