

ELU 8908A-24 HO6 396

API: 05-103-11612

Inspection: 679705121



Photo 1. Location.



ELU 8908A-24 HO6 396

API: 05-103-11612

Inspection: 679705121



Photo 2. Container next to tank battery.



Photo 3. Container next to well head.