

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2019

Submitted Date:

08/13/2019

Document Number:

679705050**FIELD INSPECTION FORM**Loc ID 316731 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Courtney, Rogers	316-636-2242	salthawk@cox.net	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Winter, Mary	316-262-4800	highrowler2@cox.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232418	WELL	PR	06/01/2019	GW	103-66126	LLOYD-FEDERAL 22-X-17	UN

**General Comment:**

COGCC Inspection Report Summary.

On 8-9-2019 at approximately 16:30, inspector Rick Moran, conducted a routine inspection at Sonterra Energy location signed as Federal 22 X 17 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Unused equipment. Photos 2, 3, 4, 5. Complete by 11-8-2019.
- 2) Stained soil at separator. Photo 6. Complete by 9-12-2019.

A voice message was left at 316-262-4800 (contact phone number at well 05-103-08096) on 8-10-2019 @ 10:00 requesting a current contact email address. The same phone number was called &amp; went to voice mail on 8-12-2019 @ 9:30.

No surface evidence of a well at this location. The battery sign is for Merrion Oil &amp; Gas well 103-66126 located 3.3 miles to the southeast. Adjacent to this location is a gas meter building signed with White Eagle &amp; Black Hills Energy with a contact number of 1-800-694-8989.

Equipment history:

- 1) On the 1990's satellite image no equipment is present.
- 2) The inspection log inside the separator is last dated May 2006 (Photo 7).
- 3) The equipment was first identified during inspection 200035623 dated 12-10-2002.
- 4) The 2009 satellite image shows the equipment.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705050.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	No evidence that the tank, compressor, or separator are in use. Equipment needs removed from the location.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/08/2019
Type	OTHER		
Comment:	Stained soil at separator.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	09/12/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	300 BBLS	STEEL AST		40.165200,-108.251300
Comment:	No label on tank. Tank appeared to be empty or near empty.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: <a href="#">Berm covered with thick vegetation.</a>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 232418 Type: WELL API Number: 103-66126 Status: PR Insp. Status: UN

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No surface evidence of a well at this location.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402143590	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908394</a>
679705051	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908388</a>