

# Interim Reclamation and Stormwater Inspection

August 14, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 453512

Inspection Document #: 697500466

Weld County, CO

SESE Section 10 T1N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 1.** Photo taken from the entrance of the location, facing West. Photo illustrates the Operator sign.



**Photo 2.** Photo taken from the entrance of the location, facing East. Photo illustrate the vehicle tracking device BMP is in need of maintenance and is not in proper functioning condition.

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 3.** Photo taken from the southern well pad, facing West. Photo illustrates unmanaged weeds throughout the topsoil stockpile.

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 4.** Photo taken from the topsoil stockpile, facing Southwest. Photo illustrates unmanaged weeds.



**Photo 5.** Photo taken from the topsoil stockpile, facing West. Appears the Operator has only mowed weeds on the top of the stockpile but not side slopes.

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 6.** Photo taken from the topsoil stockpile, facing Northwest. Photo illustrates the current state of the well, as Interim Reclamation has not yet been performed.



**Photo 7.** Photo taken from the topsoil stockpile, facing Northeast. See comments under Photo 6.

Inspection Photos

Location Name: HDI KF /01-65-10 PAD

Location ID: 453512



**Photo 8.** Photo taken from the southwestern well pad, facing South. Photo illustrates erosion that has not been repaired. Appears there was sediment discharge from location.

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 9.** Photo taken from the southwestern perimeter of location, facing East. Photo illustrates sediment discharge beyond the perimeter BMP.

Inspection Photos

Location Name: HDI KF /01-65-10 PAD

Location ID: 453512



**Photo 10.** Photo taken from the western well pad, facing West. Photo illustrates erosion that has not been repaired.



**Photo 11.** Photo taken from the northwestern well pad, facing Northwest. See comments under Photo 10.

Inspection Photos

Location Name: HDI KF /01-65-10 PAD

Location ID: 453512



**Photo 12.** Photo taken from the western MLVT area, facing North. Photo illustrates unmanaged weeds.

Inspection Photos

Location Name: HDI KF /01-65-10 PAD

Location ID: 453512



**Photo 13.** Photo taken from the western MLVT area, facing East. See comments under Photo 12.

Inspection Photos  
Location Name: HDI KF /01-65-10 PAD  
Location ID: 453512



**Photo 14.** Photo taken from the northern well pad, facing North. Photo illustrates unused equipment on location.



**Photo 15.** Photo taken from the northeastern well pad, facing Northeast. See comments under Photo 14.