

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

690004076**FIELD INSPECTION FORM**
 Loc ID 336303 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246635	WELL	SI	03/01/2019	OW	123-14432	HSR-FEDERAL 15-36	SI
290830	WELL	SI	01/01/2019	OW	123-25260	USA 37-36	SI
431996	WELL	PR	11/01/2018	OW	123-36886	USA FED 02N-36HZ	PR
431997	WELL	PR	11/01/2018	OW	123-36887	USA FED 02C-36HZ	PR
431998	WELL	PR	11/01/2018	OW	123-36888	USA FED 27N WEST-36HZ	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery location number: 431891				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities

Facility ID: 246635 Type: WELL API Number: 123-14432 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in at flow line connection to flow line.

Corrective Action: _____ Date: _____

Facility ID: 290830 Type: WELL API Number: 123-25260 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in at flow line connection to flow line.

Corrective Action: _____ Date: _____

Facility ID: 431996 Type: WELL API Number: 123-36886 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 431997 Type: WELL API Number: 123-36887 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 431998 Type: WELL API Number: 123-36888 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine inspection.	carlilec	08/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690004077	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4914871