

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

699300029**FIELD INSPECTION FORM**
 Loc ID 333132 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241516	WELL	PR	03/01/2019	OW	123-09305	KOSHIO 2	PR
241619	WELL	PR	03/23/1978	OW	123-09408	STATE OF COLORADO AF 2	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Weeds growing on lease access road and around location		
Corrective Action	Comply with rule 603.f	Date:	09/03/2019

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused electrical conduit		
Corrective Action:	Comply with Rule 603.f	Date:	09/20/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Control Panel appears turned off		

Inspected FacilitiesFacility ID: 241516 Type: WELL API Number: 123-09305 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well report shows it to be PR at time of inspection it appears to be shut in. Service valve appear to be closed

Corrective Action: _____ Date: _____

Facility ID: 241619 Type: WELL API Number: 123-09408 Status: PR Insp. Status: SI**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 8/20/19 at approximately 14:00p m, I, Inspector Robbie Revas, Conducted an on-site inspection at the State of Colorado AF #2 KP Kauffman, at API # 05-123-09408 in Weld County Colorado.</p> <p>While there, I observed a Shut in Wellsite</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Housekeeping: Weeds growing around wellsite and on lease road 603.f Corrective action date 9/3/19. See attached photos #1, #3, and #5.</p> <p>Unused equipment on location Rule 603.f Corrective action date 9/20/19. See attached photo #7.</p> <p>Reporting: Well report shows that it is a PR well, at time of inspection well appears to be Shut In, Control Panel appears to be turned off and valves appear to be closed . See attached photos #6, #8, #9.</p> <p>Weather is sunny and hot, Location is dry.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education Inspection</p>	revasr	08/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300030	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915152