

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2019

Submitted Date:

08/12/2019

Document Number:

696600467

FIELD INSPECTION FORM

Loc ID 312605 Inspector Name: Wentzel, Dougo On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1401
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222004	WELL	PR	02/01/2019	GW	077-08606	WAGON TRAIL 44-11	PR

General Comment:

[Routine FIU General Field Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Equipment:			
Type:	Bird Protectors	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Bradenhead	# 0	
Comment:			
Corrective Action:			Date:
Type:	Horizontal Heated Separator	# 1	
Comment:	I hear a gas leak at seperator, I contacted Loren Prescott to inform.		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222004 Type: WELL API Number: 077-08606 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
Gravel	Fail					
		Compaction	Pass			

Comment: Stormwater erosion not being controlled on the location at this time. BMP's not in place, need repaired or are not being maintained at this time. Erosion sediment moving off location by tank battery and choking out vegetation. See photos 6,7

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 09/12/2019

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Monday) (8/12/19) at approximately (0945) I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Wagon Trail), (API #077-08606) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Stormwater issues were observed: Sediment moving off location, by tank battery on the east side of location. BMP's not in place or needs maintenance and vegetation is being choked out from erosion sediment. See photos 6 and 7. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402144061	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908729
696600468	Inspection 696600467 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908719