

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2019

Submitted Date:

08/12/2019

Document Number:

696600471

**FIELD INSPECTION FORM**

Loc ID 429734 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 17 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429731	WELL	PR	02/26/2015	GW	077-10200	WhF DHS3C-19 D17998	PR
429732	WELL	PR	06/01/2017	OW	077-10201	WhF DHS7C-20 D17998	PR
429735	WELL	PR	06/01/2017	OW	077-10203	WhF DHS1C-19 D17998	PR
429736	WELL	PR	07/31/2015	GW	077-10204	WhF DHS3C-20 D17998	PR
429737	WELL	PR	12/01/2016	OW	077-10205	WhF DHS5C-20 D17998	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. See photos 12 and 13		
Corrective Action:	Comply with Rule 603.f .	Date:	09/12/2019
Type	OTHER		
Comment:	Soil staining around wellhead. See photos 10 and 11		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
AMINE	2	<50 BBLs	PLASTIC AST		,
Comment:	White chemical container(s) and Chemical unit(s) at wellheads				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: See other tanks				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Holes in tank containment liner. See photos 6-9				Date:
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 09/12/2019

<b>Venting:</b>	
Yes/No	NO
Comment:	
Corrective Action:	Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	429731	Type:	WELL	API Number:	077-10200	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	429732	Type:	WELL	API Number:	077-10201	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	429735	Type:	WELL	API Number:	077-10203	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	429736	Type:	WELL	API Number:	077-10204	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	429737	Type:	WELL	API Number:	077-10205	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass					
Sediment Traps	Pass					
		Gravel	Pass			
		Compaction	Pass			
Waddles	Pass					
Ditches	Pass					
Berms	Pass					
Compaction	Pass					
Rip Rap	Pass					
Gradient Terraces	Pass					
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Monday) (8/12/19) at approximately (1445) I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (WhF DHS1C D17998), (API #077-10203) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Holes in containment liner. See photos 6,7,8 and 9. Stained soil around wellhead. See photo 10 and 11. Unused equipment left on location. See photos 12 and 13. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/12/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402144065	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908741">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908741</a>
696600472	Inspection 696600471 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908721">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908721</a>