

Inspection Photos
Location Name: OASIS 42-28
API#: 05-071-06427
INSP. #: 695101188



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: OASIS 42-28
API#: 05-071-06427
INSP. #: 695101188



PHOTO 3: AREA OF IMPACTED SOIL NEAR COMPRESSOR.
Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 9/20/19.



PHOTO 4: AREA OF IMPACTED SOIL NEAR HYDRAULIC CONNECTIONS ON DRIVEHEAD ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 9/20/19.