

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/21/2019

Document Number:

696300504**FIELD INSPECTION FORM**
 Loc ID 449968 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10177Name of Operator: ENERPLUS RESOURCES (USA) CORPORATIONAddress: 950 17TH STREET #2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	720-279-5512	smiller@enerplus.com	<a href="#">All RI/CI inspections</a>
Kraich, Adam		adam.kraich@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449972	WELL	PR	10/03/2018		123-44595	CHERRY CREEK 8-67-28-27N	PR
454207	WELL	PR	10/03/2018	OW	123-46456	Barton Mills 8-67-29-30C	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead Signs are missing from both wells, See Photos #4 & #5		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/03/2019
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank Battery sign is Adequate at the entrance, but is missing at the actual Facility. Need to have Emergency Contact Info Posted at the Tanks.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/03/2019

Emergency Contact Number:

Comment: Wellheads and Tank Battery are missing Emergency Contact Info. See Photos #3, #4 &amp; #5

Corrective Action: Install sign to comply with Rule 210.d.

Date: 09/03/2019

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	NGL setup		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		

Comment:			
Corrective Action:		Date:	
Type: Compressor	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLS	STEEL AST		40.627120,-104.904550
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 449972 Type: WELL API Number: 123-44595 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 454207 Type: WELL API Number: 123-46456 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 08/20/2019 at approximately 12:02, I, Inspector Erica Petrie, conducted a Field Inspection at EnerPlus Resources (USA) Corp, at Location ID #449968 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Wellhead Signage is missing, see photo 4 &amp;5. Comply with Rule 210.d. Corrective Action date of 09/03/2019</p> <p>Battery Signage is missing, see photo 3. Comply with Rule 210.d. Corrective Action date of 09/03/2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Educational Inspection.</p>	petrie	08/21/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300525	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916096">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916096</a>