

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2019

Submitted Date:

08/22/2019

Document Number:

694900253

FIELD INSPECTION FORM

Loc ID 335338 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271799	WELL	PR	09/13/2012	GW	045-09958	ALP 19-14 (519NE)	PR
272029	WELL	PR	09/13/2012	GW	045-10004	ALP 19-11(519NE)	PR
272030	WELL	PR	09/13/2012	GW	045-10002	ALP 19-10 (K19NE)	PR
272031	WELL	PR	01/07/2008	GW	045-10003	ALP 19-15 (K19NE)	PR
272185	WELL	PR	07/05/2004	GW	045-10034	ALP 19-16 (K19NE)	PR
273574	WELL	PR	12/23/2004	GW	045-10262	ALP 19-9 (K19NE)	PR

General Comment:

routine inspection

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Type: Plunger Lift		# 6		
Comment:				
Corrective Action:				Date:
Type: Bird Protectors		# 3		
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run		# 1		
Comment:				
Corrective Action:				Date:
Type: Vertical Heated Separator		# 5		
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:				Date:
Type: Pig Station		# 1		
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLS	STEEL AST		,
Comment:	1 tank is heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	271799	Type:	WELL	API Number:	045-09958	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	272029	Type:	WELL	API Number:	045-10004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	272030	Type:	WELL	API Number:	045-10002	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	272031	Type:	WELL	API Number:	045-10003	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	272185	Type:	WELL	API Number:	045-10034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	273574	Type:	WELL	API Number:	045-10262	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Thursday 8/21/19 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus 519NE, at Location # 335338 in Garfield County, Colorado. While there, I observed normal production operations. This is a summary of inspection report.	ramseys	08/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900254	694900253	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917216