

PA 333-33

Location # 334955



Weeds have been addressed from 1/8/2019 inspection # 689702382

PA 333-33
Location # 334955



Barb wire fencing from separator fencing to location fencing is in disrepair.



Barb wire fencing from separator fencing to location fencing is in disrepair.

PA 333-33
Location # 334955



Sediment build up in diversion ditch.



Sediment build up in diversion ditch.

PA 333-33
Location # 334955



lease road from location # 323824 to location # 334955
Road rutted and needs maintained.

PA 333-33
Location # 334955



PA 333-33
Location # 334955



8" poly line running under lease road from location # 323824 to location # 334955.

PA 333-33
Location # 334955



8" poly line running under lease road from location # 323824 to location # 334955.



Line comes out on south side road is above ground with an open end.