

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2019

Submitted Date:

08/25/2019

Document Number:

693801042**FIELD INSPECTION FORM**Loc ID 312578 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
-
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	Operations Manager
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	All inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221954	WELL	SI	01/01/1984	GW	077-08556	CAMP GULCH UNIT-FEDERAL 3-22-8-103	TA

General Comment:

COGCC staff performed a routine field inspection on 8/23/2019.
 Issues were found requiring corrective action.
 See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L		Date:	
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign at separator			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			Date: _____
Corrective Action:	<input type="text"/>			
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused heated separator. CA from previous inspection not completed.			
Corrective Action:	Comply with Rule 603.f . CA date remains the same as previous inspection.		Date:	12/05/2018
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PIT			
Comment:	Hog wire and T-post			
Corrective Action:			Date:	
Equipment:				
				corrective date
Type: Horizontal Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	All guy line anchors marked. CA from previous inspection completed.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Disconnected. See Housekeeping section for CA.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	Open Top		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	No berms. Tank empty.				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221954 Type: WELL API Number: 077-08556 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [Last MIT 6/26/2012.](#)[No current MIT on record or delinquent as required by Rule 326](#)Corrective Action: [Contact dnr_cogccengineering@state.co.us with resolution plan.](mailto:dnr_cogccengineering@state.co.us)

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: 39.345173Long: -108.866315Reference Point: SEOther: Length: 10Width: 10**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801048	Inspection photos 8/23/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4918636