

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2019

Submitted Date:

08/19/2019

Document Number:

689703450

FIELD INSPECTION FORM

Loc ID 323815 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 8 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210865	WELL	PR	03/23/1998	GW	045-06623	UNION GV 10-34	PR

General Comment:

COGCC Inspection Report Summary
On Friday 08/16/2019 at approximately 1400 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra GV 10-34, at location # 323815 in Garfield County, Colorado
During this inspection the following possible compliance issues were observed:
Weeds and dead debris on location.
Comply with Rule 603.f .
C.A. Date 9/20/2019
Debris on location.
Tire chains, pipe fitting, dead debris, and cement rebar sticking out of the ground near deadman.
Comply with Rule 603.f .
C.A. Date 9/20/2019
Heated separator is not sitting level.
Ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
C.A. Date 9/20/2019
Deadman marker is bent over and not brightly colored.
Mark guy line anchors per Rule 1003.a.
C.A. Date 9/20/2019
Rills from location into road ditch. Sediment movement and build up in road ditch.
Install or repair required BMPs per Rule 1002.f.
C.A. Date 9/20/2019
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location. Tire chains, pipe fitting, dead debris, and cement rebar sticking out of the ground near deadman.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/20/2019
Type	WEEDS		
Comment:	Weeds and dead debris on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/20/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			

Corrective Action:	Date:
--------------------	-------

Equipment:		corrective date
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment: Heated separator is not sitting level.		
Corrective Action: Ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/20/2019
Type: Deadman # & Marked	# 1	
Comment: Deadman marker is bent over and not brightly colored.		
Corrective Action: Mark guy line anchors per Rule 1003.a.		Date: 09/20/2019
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 210865 Type: WELL API Number: 045-06623 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			

Comment: [Rills from location into road ditch. Sediment movement and build up in road ditch.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 09/20/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402148846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913149
689703452	Inspection 689703450 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913144