

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

699300023

**FIELD INSPECTION FORM**

Loc ID 333132 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241516	WELL	PR	03/01/2019	OW	123-09305	KOSHIO 2	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Stained soil near and around Well head and pump jack base

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/20/2019

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: Angle iron

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Ancillary equipment # 1

Comment: Electric control panel, meter, transformers

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: Electric Motor

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241516 Type: WELL API Number: 123-09305 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 8/20/19 at approximately 10:00 am, I, Inspector Robbie Revas, Conducted an on-site inspection at the Koshio #2 KP Kauffman, at API # 05-123-09305 in Weld County Colorado.                      While there, I observed Producing Wellsite                      During this inspection the following possible compliance issues were observed: Stained soil near and around well head and pump jack base. Rule 907.e 9/20/19 See attached photos #3 and #4                       A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      Continuing education Inspection.</p>	revasr	08/20/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402151137	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915155</a>
699300024	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915149</a>