

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

699300029

**FIELD INSPECTION FORM**

Loc ID 333132 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241516	WELL	PR	03/01/2019	OW	123-09305	KOSHIO 2	PR
241619	WELL	PR	03/23/1978	OW	123-09408	STATE OF COLORADO AF 2	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing on lease access road and around location		
Corrective Action:	Comply with rule 603.f	Date:	09/03/2019
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	unused electrical conduit		
Corrective Action:	Comply with Rule 603.f	Date:	09/20/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Control Panel appears turned off		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241516 Type: WELL API Number: 123-09305 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well report shows it to be PR at time of inspection it appears to be shut in. Service valve appear to be closed

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 241619 Type: WELL API Number: 123-09408 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 8/20/19 at approximately 14:00p m, I, Inspector Robbie Revas, Conducted an on-site inspection at the State of Colorado AF #2 KP Kauffman, at API # 05-123-09408 in Weld County Colorado.                      While there, I observed a Shut in Wellsite                      During this inspection the following possible compliance issues were observed:                      Housekeeping: Weeds growing around wellsite and on lease road 603.f Corrective action date 9/3/19. See attached photos #1, #3, and #5.                      Unused equipment on location Rule 603.f Corrective action date 9/20/19. See attached photo #7.                      Reporting: Well report shows that it is a PR well, at time of inspection well appears to be Shut In, Control Panel appears to be turned off and valves appear to be closed . See attached photos #6, #8, #9.                      Weather is sunny and hot, Location is dry.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      Continuing education Inspection</p>	revasr	08/20/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402151140	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915158">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915158</a>
699300030	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915152">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915152</a>