

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2019

Submitted Date:

08/27/2019

Document Number:

687905440

**FIELD INSPECTION FORM**

Loc ID 333618 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail recipient

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214950	WELL	PR	08/31/2007	GW	067-06555	FRITZ & DIGMAN 3	PR

**General Comment:**

Site inspection and quipment inventory with photos at the end of this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on sign.	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Thick vegetation of bushes and weeds around production equipment, wellhead and location.		
Corrective Action:	Control weeds per Rule 603.f.	Date:	09/06/2019

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Flow Line	# 2		
Comment:	1-2" flowline from wellhead to offsite crude oil storage tank. 1-1" flowline from wellhead to pumpjack engine fuel gas.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine on pumpjack.		
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Pumpjack engine not currently running at time of inspection.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 214950 Type: WELL API Number: 067-06555 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905449	Location weeds.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920837</a>
687905450	Wellhead weeds.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920838">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920838</a>