

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



Colorado Oil and Gas Conservation Commission  
Aug 27, 2019 14:35:01

**Photo 1 WH Sign all production flow lines have been disconnected from WH and flow lines are closed on well head. Well is TA**



Colorado Oil and Gas Conservation Commission  
Aug 27, 2019 14:35:21

**Photo 2 Unused equipment: Separator**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 3 Unused equipment: Unmarked, unused not LOTO riser.**



**Photo 4 Production flow lines on well head are closed.**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 5 TNK BTRY**



**Photo 6 Misc.. Trash**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 7 Stained soil around Crude oil tank**



**Photo 8 Stained soil under produced water load line.**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 9 Stained soil around produced water tank**



**Photo 10 Stained soil around crude oil tank.**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 11 Stained soil under Hoz sep piping**



**Photo 12 Stained soil under Hoz sep piping. Mechanical issue 2" piping leaking.**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 13 Weeds on TNK BTRY site**



**Photo 14 Weeds on TNK BTRY site**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 15 Weeds on TNK BTRY site**