

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

679705147**FIELD INSPECTION FORM**Loc ID 315243 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 2445 TECHNOLOGY FOREST BD #710City: THE WOODLANDS State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone            | Email                      | Comment                         |
|-----------------|------------------|----------------------------|---------------------------------|
| Nicol, Michael  | 281-362-8600x116 | mnicol@locinoil.com        | <a href="#">All inspections</a> |
| Kellerby, Shaun | 970-712-1248     | shaun.kellerby@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 230470      | WELL | PR     | 12/20/1977  | GW         | 103-08133 | FORK UNIT-FEDERAL 1-31 | PR          |

**General Comment:**[COGCC Inspection Report Summary.](#)[On 8-21-2019 at approximately 14:30, inspector Rick Moran, conducted a routine inspection at Locin Oil well Fork Unit Federal 1-31 in Rio Blanco county.](#)[During this inspection the following compliance issues were observed:](#)

- [1\) Tank label missing operator name. Photo 2. Complete by 10-18-2019.](#)

[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679705147.](#)

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD                                |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | TANK LABELS/PLACARDS                    |       |            |
| Comment:             | Tank label missing operator name.       |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.d. | Date: | 10/18/2019 |
| Type                 | BATTERY                                 |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Deadman # & Marked          | # 4 |       |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Tanks and Berms:**

|                    |   |          |                |         |                       |       |
|--------------------|---|----------|----------------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type           | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 1 | <50 BBLS | PBV FIBERGLASS |         | 39.925500,-108.769100 |       |
| Comment:           |   |          |                |         |                       |       |
| Corrective Action: |   |          |                |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 50 bbl   |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |                                 |                       |            |                  |
|-----------------------------|---------------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                                 |                       |            |                  |
| Facility ID: 230470         | Type: WELL                      | API Number: 103-08133 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                                 |                       |            |                  |
| Comment:                    | Producing well on plunger lift. |                       |            |                  |
| Corrective Action:          |                                 |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            |                         |                       |               |                          |         |

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402152131    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916175</a> |
| 679705148    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916170">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916170</a> |